Phone: (360) 733-1205 Fax: (888) 818-2978 Email: lab@exactscientific.com

174 56535

Water Bacteriological Analysis

Sample: 7377 Scott Pl.

Client: Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Report Date: 9/4/2025

Approved By:

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number:

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56535 | Sample: 7377 Scott PI. | | | | | | | | |
|----------------|------------------------|--------|--------------------|----------|---------|------------------|------------------|--|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |

Phone: (360) 733-1205 Fax: (888) 818-2978

Email: lab@exactscientific.com

Water Bacteriological Analysis

174 56536

Sample: 7457 Canyon View Dr.

Client: Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Approved By:

Report Date: 9/4/2025

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number: 0

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56536 | | Sample: 7457 Canyon View Dr. | | | | | | | | |
|----------------|--------------|------------------------------|--------------------|----------|---------|------------------|------------------|--|--|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | | | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | | |

Phone: (360) 733-1205 Fax: (888) 818-2978

Email: lab@exactscientific.com

Water Bacteriological Analysis

174 56537

Sample: West Reservoir Out

Client: Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Approved By:

Report Date: 9/4/2025

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number: 0

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56537 | | Sample: West Reservoir Out | | | | | | | | |
|----------------|--------------|----------------------------|--------------------|----------|---------|------------------|------------------|--|--|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | | | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | | |

Phone: (360) 733-1205 Fax: (888) 818-2978

Email: lab@exactscientific.com

Water Bacteriological Analysis

174 56538

Sample: East Reservoir Out

Client:

Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Approved By:

Report Date: 9/4/2025

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number: 0

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56538 | | Sample: East Reservoir Out | | | | | | | |
|----------------|--------------|----------------------------|--------------------|----------|---------|------------------|------------------|--|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |

Phone: (360) 733-1205 Fax: (888) 818-2978

Email: lab@exactscientific.com

Water Bacteriological Analysis

174 56539

Sample: Reservoir In

Client:

Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Report Date: 9/4/2025

Approved By:

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number: 0

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56539 | Sample: Reservoir In | | | | | | | | |
|----------------|----------------------|--------|--------------------|----------|---------|------------------|------------------|--|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |

Phone: (360) 733-1205 Fax: (888) 818-2978

Email: lab@exactscientific.com

Water Bacteriological Analysis

174 56540

Sample: 7554 Olsen Dr.

Client: Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Approved By:

Report Date: 9/4/2025

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number: 0

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56540 | Sample: 7554 Olsen Dr. | | | | | | | |
|----------------|------------------------|--------|--------------------|----------|---------|------------------|------------------|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | |

Phone: (360) 733-1205 Fax: (888) 818-2978

Email: lab@exactscientific.com

Water Bacteriological Analysis

174 56541

Sample: 7481 Miller Way

Client:

Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Approved By:

Report Date: 9/4/2025

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number: 0

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56541 | | Sample: 7481 Miller Way | | | | | | | |
|----------------|--------------|-------------------------|--------------------|----------|---------|------------------|------------------|--|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | |

Phone: (360) 733-1205 Fax: (888) 818-2978 Email: lab@exactscientific.com

174 56542

Water Bacteriological Analysis

Sample: 7457 Canyon View Dr.

Client: Glacier Springs Water System

PO Box 126

Maple Falls, WA 98226

Phone: (360) 739-3933

Email: john@watersystemservices.net

Invoice Number: 25-16076

PO Number:

Project Name:

Approved By:

Report Date: 9/4/2025

Sample Information

Date Collected: 9/2/2025 Date Received: 9/3/2025

Sample Collected by: IC Source Number: 0

Sample Purpose: Investigative

Sample Type: Post Treatment/Finished Water Sample Chlorine Res:

Sample Composition: Coliform Samples

Sample Collection: Flowing
Suitability: Yes

System Number: 27755

| Lab #: 56542 | | Sample: 7457 Canyon View Dr. | | | | | | | | |
|----------------|--------------|------------------------------|--------------------|----------|---------|------------------|------------------|--|--|--|
| Analyte | Results | Units | Detection Limit | Method | Analyst | Date Analyzed | Date Approved | | | |
| TOTAL COLIFORM | Satisfactory | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | | |
| E. COLI | Absent | /100ml | 1 | SM_9223B | KR | 9/4/2025 | 9/4/2025 | | | |