

Water Bacteriological Analysis

174 14368

Sample: 7457 Canyon View Dr. S01
Client: Glacier Springs Water System
PO Box 126
Maple Falls, WA 98226

Invoice Number: 26-04315

PO Number:

Project Name:

Report Date: 3/3/2026

Phone: (360) 739-3933

Email: john@watersystemservices.net

Approved By:



Sample Information

Date Collected:	3/2/2026	Date Received:	3/2/2026
Sample Collected by:	IC	Source Number:	0
Sample Purpose:	Routine Compliance	Residual Chlorine:	Total:
Sample Type:	Post Treatment/Finished Water Sample		Free:
Sample Composition:	Coliform Samples		
Sample Collection:	Flowing		
Suitability:	Yes		

System Number: 27755

System Name: GLACIER SPRINGS WATER SYSTEM

Lab #: 14368		Sample: 7457 Canyon View Dr. S01					
Analyte	Results	Units	Detection Limit	Method	Analyst	Date Analyzed	Date Approved
TOTAL COLIFORM	Satisfactory	/100ml	1	SM_9223B	KR	3/3/2026	3/3/2026
E. COLI	Absent	/100ml	1	SM_9223B	KR	3/3/2026	3/3/2026